# **AP 09**



Absolute Electronic Indicator AP09 is used for applications requiring automatic data transmission of machine parameters via interface to a PC or control. Position and target values are indicated in the easily read LED-display. Easy mounting via hollow shaft plus the battery-backedup display allow a fast and safe machine set up.

#### **Features**

- · LED display
- · Absolute, battery-backed-up
- BUS-interface (RS485)
- Programmable parameters: pitch, calibration value, counting direction, target / position value display
- · Multifunction key which is programmable as reset, incremental measurement or target value

#### **Accessories**

- · Programming software for PC
- Gateways for different BUS-systems (eg. CAN-BUS, Interbus-S, Profibus)
- BUS-terminating plug (BAS09).

#### **Technical data**

Housing: reduced interference

susceptibility

Colour of housing: black

Weight:

Hollow shaft [ø mm]:

Speed (on shaft):

(mains supply) (battery-powered) Working temperature:

Storage temperature:

Humidity:

Vibration allowed:

Shock allowed:

Protection:

composite material, with

approx. 250 g

20<sup>H7</sup> friction bearing

≤ 500 rpm ≤ 300 rpm

0 to + 50 ° C

-20 to + 80 ° C.

0 to 95%, condensation

not permitted

10 g (5 to 150 Hz)

accord. to DIN IEC 68-2-6 20 g (100 to 2000 Hz)

30 g (15 ms)

accord. to DIN IEC 68-2-27

IP50 (option IP54)

#### **Electrical data**

Supply voltage: 24 V d.c. +/-20 %,

with built-in polarity

protection

Power consumption: < 0.5 W

Display: 5 x 7-segment-LED, 8 mm

Max. counting range: ± 6900 revolutions - 19999 to + 99999 Max. display range: Interface: RS485; 115.2 kBaud Connection: 2 circular connector address / zero point /incre-Key functions:

mental measurement /

target value

Parameters: programmable via interface Lithium 3 V battery type CR Battery:

17335, battery life approx.

6 years


noise immunity class 3, Noise immunity:


accord. to IEC 801-3


Test mark: CE-sign


Resolution: ≤ 600 steps/revolution

# **AP 09**











# **Accessories / Option**



# **Reducing sleeves**

These are used to adapt the diameters of driving shaft and position indicator. For ordering reducing sleeves separately, please refer to the table below. If you order complete position indicators, the necessary reducing sleeve will be automatically supplied with the indicator according to the hollow shaft bore diameter specified.

[mm]	RH01	RH02	RH03	RH04	RH07
ød <sub>1</sub> <sup>H7</sup>		16, 20, 22 24, 25, 26	20, 22	6, 8, 10, 12	6, 8
ød <sub>2</sub>	5,5	5,5	5,5	4,2	3,2
øD <sub>f7</sub>	20	30	25	14	10
Α	4,5	4,5	4,5	3,5	2,5
В	20	30	30	17	14
Indicator	DA 05/1 DA 08 DA 09 DE 09 AP 09	DA 10 (shaft WK)	DA 10 (shaft WL)	DA 03 DA 04	DA 02



#### Crank handles and handwheels


Auxiliaries such as handwheels or crank handles may be used for spindle adjustment. Please inquire!



## **Arrow symbols**

For extra indication of the counting direction, DA04 and DA09 indicators are available with the option 'direction arrow'. Please ask for detailed technical information

# Mounting instructions




### Torque pin mounting

The radius of the hollow shaft is to be added to the distance between hollow shaft axis and torque pin axis. Use caliper gauge and scriber to draw this dimension onto the mounting surface, then center and bore (for bore diameter and depth refer to technical drawing).

After careful preboring the Position Indicators can be mounted without strain.

Screw in / tighten grub screw to fix the shaft. If an axial seal is used, grub screw has to be screwed in flush (if necessary, provide for a recess in the shaft).




# **Torque pins**

Some Position Indicators are available with two different torque pin types. Umbrella-shaped torque pin type B is especially suitable for compensating mounting tolerances.

#### **Axial seal**

When using an axial seal, the grub screw has to be screwed in flush. If necessary, provide for a recess in the shaft.



## Change of counting direction

Position Indicators type DA 05/1 and DA 08 offer the possibility to modify the counting direction subsequently. First of all remove the housing. Then unscrew the locking screws and shift the bevel gears on the axis. Retighten locking screws. Ensure that bevel gears are correctly engaged and move smoothly.

For clockwise increasing values the left bevel gear must be engaged (viewed from device's rear).