
AG04B

Stellantrieb

| Originalmontageanleitung | Deutsch | Seite 2 |
|---|---------|----------------|
| Actuator | | |
| Translation of the Original Installation Instructions | English | page 26 |





Deutsch

- 2

Inhaltsverzeichnis

| 1 | Dokumentation | 3 |
|---|--|----|
| 2 | Sicherheitshinweise | 3 |
| | 2.1 Bestimmungsgemäße Verwendung | 3 |
| | 2.2 Kennzeichnung von Gefahren und Hinweisen | 3 |
| | 2.3 Zielgruppe | 4 |
| | 2.4 Grundlegende Sicherheitshinweise | 5 |
| 3 | Identifikation | 6 |
| 4 | Installation | 6 |
| | 4.1 Mechanische Montage | 6 |
| | 4.2 Elektrische Installation | 8 |
| | 4.3 Belegung der DIP-Schalter | 9 |
| | 4.4 Anschlussbelegung EX | 10 |
| | 4.5 Anschlussbelegung E1/PG (Klemmenkasten) | 11 |
| 5 | Inbetriebnahme | 15 |
| 6 | Transport, Lagerung, Wartung und Entsorgung | 19 |
| 7 | Zubehör Anschluss-Stecker | 19 |
| • | 7.1 Gegenstecker M16 gerade | 19 |
| | 7.2 Gegenstecker M16 inkl. Kabel | 20 |
| | 7.3 Gegenstecker M16 gewinkelt | 21 |
| | 7.4 Gegenstecker M12 gewinkelt | 22 |
| 8 | Technische Daten | 23 |
| a | Finhauerklärung | 25 |



1 Dokumentation

Zu diesem Produkt gibt es folgende Dokumente:

- Datenblatt beschreibt die technischen Daten, die Abmaße, die Anschlussbelegungen, das Zubehör und den Bestellschlüssel.
- Montageanleitung beschreibt die mechanische und die elektrische Montage mit allen sicherheitsrelevanten Bedingungen und der dazugehörigen technischen Vorgaben.
- Benutzerhandbuch und Softwarebeschreibung zur Inbetriebnahme und zum Einbinden des Stellantriebes in ein Feldbussystem.

Diese Dokumente sind auch unter "http://www.siko-global.com/p/ag04b" zu finden.

2 Sicherheitshinweise

2.1 Bestimmungsgemäße Verwendung

Der Stellantrieb AG04B dient für Verstellaufgaben an Anlagen und Maschinen. Der Stellantrieb ist nur für die Verwendung im Industriebereich vorgesehen die keinen besonderen elektrischen oder mechanischen Sicherheitsanforderungen unterliegen.

- 1. Beachten Sie alle Sicherheitshinweise in dieser Anleitung.
- Eigenmächtige Umbauten und Veränderungen an dem Stellantrieb sind verboten.
- 3. Die vorgeschriebenen Betriebs- und Installationsbedingungen sind einzuhalten.
- 4. Der Stellantrieb darf nur innerhalb der technischen Daten und der angegebenen Grenzen betrieben werden (siehe Kapitel 8).

2.2 Kennzeichnung von Gefahren und Hinweisen

Sicherheitshinweise bestehen aus dem Signalzeichen und einem Signalwort.

Gefahrenklassen



Unmittelbare Gefährdungen die zu schweren irreversiblen Körperverletzungen mit Todesfolge, Sachschäden oder ungeplanten Gerätereaktionen führen können, sofern Sie die gegebenen Anweisungen missachten.



Sicherheitshinweise



Gefährdungen die zu schweren Körperverletzungen, Sachschäden oder ungeplanten Gerätereaktionen führen können, sofern Sie die gegebenen Anweisungen missachten.



Gefährdungen die zu leichten Verletzungen, Sachschäden oder ungeplanten Gerätereaktionen führen können, sofern Sie die gegebenen Anweisungen missachten.

ACHTUNG

Wichtige Betriebshinweise die die Bedienung erleichtern oder die bei Nichtbeachtung zu ungeplanten Gerätereaktionen führen können und somit möglicherweise zu Sachschäden führen können.



Signalzeichen

2.3 Zielgruppe

Montageanleitung und Benutzerhandbuch wenden sich an das Projektierungs-, Inbetriebnahme- und Montagepersonal von Anlagen- oder Maschinenherstellern, das über besondere Kenntnisse innerhalb der Antriebstechnik verfügt. Dieser Personenkreis benötigt fundierte Kenntnisse über die notwendigen Anschlüsse eines Stellantriebs und dessen Integration in die komplette Maschinenanlage.

WARNUNG

Nicht ausreichend qualifiziertes Personal

Personenschäden, schwere Schäden an Maschine und Stellantrieb werden durch nicht ausreichend gualifiziertes Personal verursacht.

- Projektierung, Inbetriebnahme, Montage und Wartung nur durch geschultes Fachpersonal.
- Dieses Personal muss in der Lage sein, Gefahren, welche durch die mechanische, elektrische oder elektronische Ausrüstung verursacht werden können, zu erkennen.

Oualifiziertes Personal

sind Personen, die

- als Projektierungspersonal mit den Sicherheitsrichtlinien der Elektround Automatisierungstechnik vertraut sind;
- als Inbetriebnahme- und Monatagepersonal berechtigt sind, Stromkreise und Geräte/Systeme gemäß den Standards der Sicherheitstechnik in Betrieb zu nehmen, zu erden und zu kennzeichnen.



Deutsch

2.4 Grundlegende Sicherheitshinweise

▲ GEFAHR

Explosionsgefahr

Stellantrieb nicht in explosionsgefährdeten Zonen einsetzen.

▲ GEFAHR

Ungebremster Stellantrieb

Sofortigen Verlust des Drehmoments bei Spannungsausfall, Störungen und Freischalten der Endstufe/Steuerung. Der Stellantrieb wird nicht gebremst.

Externe Haltevorrichtungen verwenden (z. B. NOT-STOP Haltebremse).

WARNUNG

Rotierende Teile

Quetschungen, Reibung, Abschürfen, Erfassen von Gliedmaßen und Kleidung durch Berühren von rotierende Teile wie z. B. Klemmring, Drehmomentstütze oder Hohlwelle im Betrieb.

Zugriffsmöglichkeit durch Schutzmaßnahmen verhindern.

WARNUNG

Heiße Oberflächen

Verbrennungen durch Temperaturen >60 °C an der Gehäuseoberfläche während des Betriebs.

- ▶ Zugriffsmöglichkeit auf Gehäuse verhindern.
- Temperaturempfindliche Anlagenteile durch Schutzmaßnahmen schützen.

WARNUNG

Wohnumgebung

Hochfrequente Störungen in Wohnumgebungen.

Dieser Stellantrieb ist nicht für den Einsatz in einem öffentlichen Niederspannungsnetz vorgesehen, das Wohngebiete speist.

!VORSICHT

Hohe Rückspeisung

Bei kundenseitigem hohem Trägheitsmoment und gleichzeitigem Abbremsen kann der Stellantrieb in den generatorischen Betrieb übergehen. D. h. mechanische Energie wird in elektrische Energie umgewandelt und ins Versorgungsnetz zurückgespeist. Das Netzteil muss die entstehende Energie aufnehmen, ansonsten werden andere angeschlossene Verbraucher zerstört.

- Setzen Sie nur Netzteile mit großer Ausgangskapazität (>10.000 μF)
 bzw. rückspeisefähige Netzteile ein.
- Verwenden Sie bei Bedarf eine entsprechenden Bremswiderstandsansteuerung.
- Prüfen Sie ob alle Verbraucher für Rückspeisespannungen ausgelegt sind.




Externe Magnetfelder

Es kommt zu Betriebsstörungen und Datenverlust, wenn starke externe Magnetfelder das interne Messsystem beeinflussen.

Schützen Sie den Stellantrieb vor Einflüssen von Fremdmagneten.

3 Identifikation

Das Typenschild zeigt den Gerätetyp mit Variantennummer. Die Lieferpapiere ordnen jeder Variantennummer eine detaillierte Bestellbezeichnung zu.



4 Installation

4.1 Mechanische Montage

WARNUNG

Ausfall Stellantrieb

Verlust der Schutzart durch Verschleiß der Dichtringe im Kugellager und Radialwellendichtringe.

 Stellantrieb innerhalb der zulässigen Parameter (siehe Kapitel 8) betreiben.

/ VORSICHT

Zerstörung Hauptlager

Unsachgemäße Montage (z. B. Spannungen an der Antriebswelle) führt zu zusätzlicher Erwärmung und langfristig zur Zerstörung des Stellantriebes.

 Sorgen Sie für einen geringen Wellen- und Winkelversatz zwischen Welle und Aufnahmebohrung durch geeignete Fertigungsmaßnahmen (siehe Abb. 1 + Tab. 1).

!VORSICHT

Ausfall Stellantrieb

- IP-Schutzart bei Montage beachten (siehe Kapitel 8).
- Schutzartbedingt alle Gegenstecker (siehe Kapitel 7) mit ≥1 Nm an den Stellantrieb schrauben.
- ▶ Stellantrieb nicht selbst öffnen (Ausnahme siehe Kapitel 4.5 + 5).
- Schläge auf das Gerät vermeiden.
- Keinerlei Veränderung am Gerät vornehmen.



Vorbereitung Montage (Abb. 1, Abb. 2, Abb. 3):

- 1. Bohrung (øD) auf Abstand (L1) zur Antriebswelle (2) fertigen.
- 2. Länge (L2) und Durchmesser (ød) der Welle ② beachten.
- 3. M5 Schraube in der Drehmomentstütze 1 und M4 Schraube im Klemmring 3 lockern.

Montage (Abb. 1, Abb. 2, Abb. 3):

- 1. Stellantrieb auf Welle (2) schieben bis Drehmomentstütze (1) auf Anschlag ist. Drehmomentstütze lässt sich über ein Langloch den Einbauverhältnissen geringfügig anpassen.
- 2. Klemmringschraube (3) mit 10 Nm anziehen.
- 3. Schraube für Drehmomentstütze 1 mit ≤2 Nm anziehen.




Abb. 1: Einbaumaße

| Maß øD | ø13 ø14 |
|--------|--------------|
| Maß L1 | 106.7 |
| Maß L2 | 40 45 |
| Maß ød | Ø20f8; Ø14f8 |

Tab. 1: Einbaumaße

Abb. 2: Montage

- Drehmomentstütze
- (2) Welle
- 3 Klemmringschraube




Abb. 3: Anzugsmoment Schrauben

4.2 Elektrische Installation

WARNUNG

Zerstörung von Anlagenteilen und Verlust der Steuerungskontrolle

- Anschlussverbindungen nicht unter Spannung schließen oder lösen.
- Verdrahtungsarbeiten spannungslos durchführen.
- Litzen mit geeigneten Aderendhülsen versehen.
- Vor dem Einschalten sind alle Leitungsanschlüsse und Steckverbindungen zu überprüfen.
- Betriebsspannung gemeinsam mit der Folgeelektronik (z. B. Steuerung) einschalten.

WARNUNG

Unvorhergesehene Geräteaktionen des Stellantriebs oder anderer Geräte

Der Stellantrieb ist gegen EMV Ein- und Ausstrahlung (Elektromagnetische Verträglichkeit) geschützt. Zu starke externe EMV Strahlung kann zu unvorhergesehene Aktionen des Stellantriebs führen (z. B. Zerstörung des Stellantriebs; Stellantrieb setzt sich in Bewegung; Positionswertverlust). Nicht EMV geschützte Geräte, die zu nah am Stellantrieb in Betrieb sind, können gestört werden.

- Führen Sie die Verdrahtung gemäß den EMV-Maßnahmen IEC 61800-3 und Kapitel 4.2 durch.
- Überprüfen Sie die korrekte Ausführung der EMV-Maßnahmen.

WARNUNG

Brandgefahr

Zum Schutz von Folgeschäden bei Gerätedefekten ist eine Absicherung erforderlich.

- Hierzu bieten sich elektronische Sicherungsautomaten der Firma E-T-A bzw. Lastkreisüberwachungen der Firma Murr Elektronik an.
- Die Nennströme sind den technischen Daten in Kapitel 8 zu entnehmen.

VORSICHT

Elektromagnetische Verträglichkeit (EMV)

Um die elektromagnetische Verträglichkeit des Stellantriebs zu gewährleisten sind folgende Maßnahmen erforderlich:

- Separates Netzteil zur Versorgung eines oder mehrerer SIKO-Stellantriebe vorsehen.
- Alle Leitungen für den Stellantrieb müssen geschirmt sein.
- Der Kabelschirm muss beidseitig aufgelegt sein.
- Klappferrit (im Lieferumfang) an der Versorgungsleitung dicht am 3 pol. Steckverbinder anbringen.
- Erdung des Antriebes über den vorgesehenen Flachsteckeranschluss mit einem Litzenguerschnitt von ≥4 mm².





ACHTUNG

Alle Anschlüsse sind prinzipiell gegen äußere Störeinflüsse geschützt. Der Einsatzort ist so zu wählen, dass induktive oder kapazitive Störungen nicht auf den Stellantrieb oder dessen Anschlussleitungen einwirken können. Das System in möglichst großem Abstand von Leitungen einbauen, die mit Störungen belastet sind. Gegebenenfalls sind zusätzliche Maßnahmen, wie Schirmbleche oder metallisierte Gehäuse vorzusehen.

Zulässige Leistungsaufnahme

ACHTUNG

Die Versorgung für den Stellantrieb ist ausreichend zu dimensionieren. Die Stromaufnahme kann beim Beschleunigen kurzzeitig höher sein als der Nennstrom. Die Spannungswerte sind abhängig von der Geräteausführung und sind den technischen Daten in Kapitel 8 zu entnehmen.

Motorsteuerung + Endstufe

- Litzenquerschnitt ≥0.75 mm²
- Motorsteuerung und Endstufe werden gemeinsam über den Anschluss Betriebsspannung versorgt.

Digitaleingänge

• 15 ... 30 V DC; typ. 10 mA

4.3 Belegung der DIP-Schalter

| Schalter | Belegung |
|-----------|--|
| SW1-SW7 | Busadresse: siehe Kapitel Profibus - Adresseinstellung |
| SW8 | keine Funktion: Stellung immer auf OFF |
| SW9 | Anschlussart EX: Stellung immer auf ON Anschlussart E1/PG: siehe Kapitel Anschlussbelegung E1 / PG, Klemmleiste X3 |
| SW10 | Endschaltereingänge deaktivieren: siehe Kapitel Endschaltereingänge 1+2 |
| SW11+SW12 | Busabschluss: siehe Kapitel Profibus - Busabschluss |

AGO4B Installation

4.4 Anschlussbelegung EX




Abb. 4: Anschluss EX


- 1 Erdung (3x 6.3)
- (2) Betriebsspannung
- 3 Eingänge
- 4 Bus-Ein
- 5 Bus-Aus

Betriebsspannung

Stift 3 pol.

Zubehör Gegenstecker und Kabelverlängerungen siehe Kapitel 7.

| PIN | Belegung | |
|-----|----------|--|
| 1 | +24 V | |
| 2 | Freigabe | |
| 3 | GND | |




Profibus-DP

- Bus-Ein: Stift 5 pol.
- Bus-Aus: Buchse 5 pol.

Zubehör Gegenstecker und Kabelverlängerungen siehe Kapitel 7.

| PIN | Belegung | |
|-----|----------|--|
| 1 | nc | |
| 2 | BUS A | |
| 3 | nc | |
| 4 | BUS B | |
| 5 | nc | |



Eingänge

ACHTUNG


Bei Anschlussart EX besteht keine galvanische Trennung der Digitaleingänge!

• Stift 8 pol.

Zubehör Gegenstecker und Kabelverlängerungen siehe Kapitel 7.



| PIN | Belegung |
|-------|---------------|
| 1 | Endschalter 1 |
| 2 | Endschalter 2 |
| 3 | Eingang 1 |
| 4 | Eingang 2 |
| 5 - 7 | nc |






Abb. 5: Eingangsschaltung Digitaleingänge bei Anschlussart EX

4.5 Anschlussbelegung E1/PG (Klemmenkasten)

▲ GEFAHR

Überlastung

Überlastung der Leiterbahnen bei Durchschleifen der Anschlüsse +24 V/GND/Schirm.

▶ Gesamtstrom 20 A nicht überschreiten!

WARNUNG

Zerstörung des Stellantriebs

Nichtbeachtung führt zum Verlust des Verpolschutzes und somit zur Zerstörung des Stellantriebs.

Den Anschluss Klemmleiste X3.7 (GND) nur verwenden, um eine Brücke zum Anschluss Klemmleiste X3.6 (EXT_GND) herzustellen.

NORSICHT

Ausfall Stellantrieb

Werden die Anschlüsse "Betriebsspannung Aus", "Bus-Aus" oder "Eingänge", nicht verwendet, kommt es zum Verlust der Schutzart.

- ▶ Mitgelieferte Verschlusskappen im Klemmenkasten verwenden.
- Bei Montage des Deckels auf korrekten Sitz der Dichtung achten.





Abb. 6: Anschluss E1/PG (5x PG9)

- 1) Erdung (3x 6.3)
- (2) Betriebsspannung Ein
- Betriebsspannung Aus
- (4) Eingänge
- Bus-Ein
- (6) Bus-Aus

Demontage/Montage Klemmenkasten

Nach Lösen der 6 Schrauben und entfernen des Deckels sind die Klemmleisten zugänglich.



- 1) Klemmleiste X1
- (2) Klemmleiste X2
- 3) Klemmleiste X3
- 4 Leiterplatten-Nr.

Abb. 7: Montagebeispiel (Kabel nicht im Lieferumfang!)

Klemmleiste X1 (Betriebsspannung)

Klemmbereich ohne Aderendhülse: 0.13 ... 2.5 mm².

Klemmbereich mit Aderendhülse (6 mm): 0.25 ... 1.5 mm².

Bei der Auswahl des Aderquerschnittes ist die Kabellänge entsprechend zu berücksichtigen (Leistungsverluste).



| Klemme X1 | Belegung |
|-----------|-------------------------------|
| 1 | +24 V (Betriebsspannung Aus) |
| 2 | +24 V (Betriebsspannung Ein) |
| 3 | GND (Betriebsspannung Aus) |
| 4 | GND (Betriebsspannung Ein) |
| 5 | Schirm (Betriebsspannung Aus) |
| 6 | Schirm (Betriebsspannung Ein) |

Klemmleiste X2 (Profibus-DP)

Profibuskabel nach Norm EN 50170.

| Klemme X2 | Belegung |
|-----------|----------|
| 1 | BUS B |
| 2 | BUS A |
| 3 - 8 | nc |
| 9 | BUS A |
| 10 | BUS B |

Klemmleiste X3 (Eingänge)

ACHTUNG

Die Eingänge sind bei der Anschlussart E1/PG prinzipiell galvanisch von GND getrennt. Soll die galvanische Trennung aufgehoben werden, sind die Signale Klemmleiste X3.6 (EXT_GND) und Klemmleiste X3.7 (GND) zu verbinden. Ab der Leiterplatten-Nr. 84403.2 gilt: Soll die galvanische Trennung aufgehoben werden, so ist der Dipschalter 9 zu betätigen (on). Die Leiterplatten-Nr. ist zwischen X1 und X2 auf der Leiterplattenoberfläche zu erkennen (Abb. 7).

Klemmbereich ohne Aderendhülse: 0.2 ... 1.5 mm². Klemmbereich mit Aderendhülse (8 mm): 0.25 ... 1.5 mm².




Abb. 8: Eingangsschaltung Digitaleingänge bei Anschlussart E1/PG


| Klemme X3 | Belegung |
|-----------|---------------|
| 1 | Endschalter 1 |
| 2 | Endschalter 2 |
| 3 | Eingang 1 |



| Klemme X3 | Belegung |
|-----------|-----------|
| 4 | Eingang 2 |
| 5 | Freigabe |
| 6 | EXT_GND |
| 7 | GND |

Anschluss Kabel E1/PG

- Die Kabel gemäß Abb. 9 vorbereiten. Aderendhülsen müssen mit gasdichter Vierkant-Crimpung versehen sein.
- Öffnen Sie das Gerät (siehe Kapitel 4.5) und demontieren Sie die PG-Verschraubung.



Maß Maß Maß C Α В Betriebsspannung 70 6 12 Profibus-DP 70 12 8 70 8 12 Eingänge

Abb. 9: Kabel

Tab. 2: Kabelmaße

(1) Litzen abisoliert und **nicht** verzinnt

Anschluss Kabelverschraubung

- Schieben Sie die Mutter mit Dichtungsgummi (1), Scheibe (2) (Innen-ø > Innen-ø Scheibe (4)) und Scheibe (4) auf das Kabel.
- Das Abschirmgeflecht 3 über die Außenfläche der Scheibe 2 zurückstülpen.
- 3. Litzen durch die Verschraubung (5) schieben. Einpassen der Teile (4), (3), und (2) in die Verschraubung (5).
- 4. Die Mutter ① aufschrauben und die komplette Verschraubung am Deckel anbringen.
- 5. Litzen an der Klemmleisten des Gerätes anschliessen (siehe Kapitel 4.5).




Abb. 10: Kabelverschraubung PG9



Anschluss Erdung (PE)

Zum Schutz vor Störungen müssen die Schirme der Signalleitungen und Netzleitung beidseitig angeschlossen werden. Potentialunterschiede führen zu unzulässigen Strömen auf dem Schirm. Den PE Anschluss ① zwischen den Anschlusssteckern auf das Schutzleiterpotential legen (siehe Abb. 4 oder Abb. 6). Verwenden Sie dazu 6.3 mm Flachstecker mit kurzer Litze 2.5 ... 4 mm² (nicht im Lieferumfang). Bei mehreren Stellantrieben wird empfohlen die Erdung auf eine PE-Schiene ① anzuschließen (siehe Abb. 11).




Abb. 11: PE-Schiene

5 Inbetriebnahme



Latchup-Effekte

Ausgangsstufe des Treibers wird beschädigt.

 Die Betriebsspannung des Gerätes muss gemeinsam mit der Folgeelektronik (z. B. Steuerung) eingeschaltet werden.

Bitte beachten Sie die Hinweise auf ordnungsgemäßen mechanischen und elektrischen Anschluss. Nur dann sind die Voraussetzungen für eine problemlose Inbetriebnahme und einwandfreien Betrieb gegeben.

Prüfen Sie vor der Inbetriebnahme insbesondere nochmals auf:

- korrekte Polung der Betriebsspannung.
- korrekten Anschluss der Kabel und Signale.
- festen Sitz des Stellantriebes und der Hohlwelle.
- korrekte Montage und Funktion der Endschalter.




Abb. 12: DIP-Schalter

- 1 DIP-Schalter
- (2) Profibus-LED (orange)
- (3) Status-LED (rot/grün)
- (4) Taste für Tippbetrieb Linkslauf (Ansicht auf Klemmring)
- (5) Taste für Tippbetrieb Rechtslauf (Ansicht auf Klemmring)

Profibus-DP

ACHTUNG

- Die Drehrichtung im Tipptastenbetrieb ist vom Parameter "Drehrichtung" unabhängig.
- Der Tipptastenbetrieb ist nur verfügbar, wenn sich der Profibus Zustandsautomat des Stellantriebes nicht im Zustand Data Exchange hefindet.

Nach ordnungsgemäßer Montage und Verdrahtung kann der Stellantrieb durch Einschalten der 24 V Versorgung in Betrieb genommen werden.

Freigabeeingang

Um den Stellantrieb in Bewegung setzen zu können, muss am Freigabeeingang ein High – Pegel anliegen. Somit ist eine Verdrahtung dieses Eingangs zum Betrieb zwingend. Liegt am Freigabeeingang kein High - Pegel an, leuchtet die Status – LED rot. Grünes Leuchten der Status – LED signalisiert, dass der Freigabeeingang aktiv und der Stellantrieb betriebsbereit ist.

Endschaltereingänge 1+2

Die beiden Low – aktiven Endschaltereingänge können über den DIP – Schalter SW10 deaktiviert werden (siehe Abb. 12).

| SW10 | Endschalter | Bemerkung |
|------|-------------|--|
| OFF | aktiv | Verdrahtung der Endschalter zwingend erforderlich. |
| ON | deaktiviert | Keine Verdrahtung der Endschalter nötig. |

Die Anordnung der Endschalter erfolgt unabhängig von der parametrierten Drehrichtung:






Abb. 13: Endschalter

- Endschalter 1
- (2) Endschalter 2

Die Endschaltereingänge sind der mechanischen Drehrichtung fest zugeordnet (siehe Abb. 13). Bei aktivem Endschalter 1 ist eine motorische Verstellung in Richtung "Endschalter 1" nicht mehr möglich. Entsprechend gilt dies auch für Endschalter 2.

Eingänge 1+2

Die beiden Zusatzeingänge sind Low - aktiv.

Profibus - Adresseinstellung

WARNUNG

Ausfall Stellantrieb

- Schutzartbedingt nur die Innensechskantschrauben (1) lösen (siehe Abb. 14).
- Bei gelösten Schrauben 1 des Deckels 2 ist die Schutzart des Stellantriebes nicht mehr gewährleistet.
- ▶ Parameter am DIP-Schalter (3) einstellen.
- Bei Wiedermontage der Schrauben ① auf korrekten Sitz der Dichtung ④ achten!

ACHTUNG

Die DIP - Schaltereinstellungen werden nur beim Einschalten der Versorgungsspannung eingelesen. Eine Änderung der Slave - Adresse während des Betriebs hat keine Auswirkungen.

Nach Lösen der 4 Schrauben 1 und entfernen des Deckels 2 ist der DIP-Schalter 3 für die Adresseinstellung zugänglich.




Abb. 14: Adresseinstellung

- 1 Schrauben
- 2 Deckel
- 3 DIP-Schalter
- 4 Dichtung

Die Eingabe der Slave - Adresse erfolgt über die Schalter 1 - 7 im Binärformat. Die Einstellung der Adresse 127 wird intern in die Adresse 126 umgesetzt.

Folgende Tabelle verdeutlicht dies:

| SW1 [2º] | SW2 [2 ¹] | SW3 [2 ²] | SW4 [2³] | SW5 [2 ⁴] | SW6 [2 ⁵] | SW7 [2 ⁶] | eingestellte Slave-Adresse |
|-------------|--------------------------|--------------------------|-------------|--------------------------|--------------------------|--------------------------|-------------------------------|
| OFF | OFF | OFF | OFF | OFF | OFF | OFF | 0 |
| ON | OFF | OFF | OFF | OFF | OFF | OFF | 1 |
| OFF | ON | OFF | OFF | OFF | OFF | OFF | 2 |
| ON | ON | OFF | OFF | OFF | OFF | OFF | 3 |
| : | : | : | : | : | : | : | : |
| OFF | OFF | ON | ON | ON | ON | ON | 124 |
| ON | OFF | ON | ON | ON | ON | ON | 125 |
| OFF | ON | ON | ON | ON | ON | ON | 126 |
| ON | ON | ON | ON | ON | ON | ON | 126! |

Profibus - Busabschluss

Über die DIP - Schalter 11 + 12 kann der interne Busabschluss aktiviert werden:

| SW11 | SW12 | Busabschluss |
|------|------|--------------|
| OFF | OFF | deaktiviert |
| ON | ON | aktiv |

Deutsch

6 Transport, Lagerung, Wartung und Entsorgung

Transport und Lagerung

Stellantriebe sorgfältig behandeln, transportieren und lagern. Hierzu sind folgende Punkte zu beachten:

- Stellantriebe in der ungeöffneten Originalverpackung transportieren und/oder lagern.
- Stellantriebe vor schädlichen physikalischen Einflüssen wie Staub, Hitze und Feuchtigkeit schützen.
- Anschlüsse weder durch mechanische noch durch thermische Einflüsse beschädigen.
- Vor Montage ist der Stellantrieb auf Transportschäden zu untersuchen.
 Beschädigte Stellantriebe nicht einbauen.

Wartung

Bei korrektem Einbau nach Kapitel 4 ist der Stellantrieb wartungsfrei. Der Stellantrieb enthält eine Lebensdauerschmierung und muss unter normalen Betriebsbedingungen nicht nachgeschmiert werden.



Entsorgung

Die elektronischen Bauteile des Stellantriebes enthalten umweltschädigende Stoffe und sind zugleich Wertstoffträger. Der Stellantrieb muss deshalb nach seiner endgültigen Stilllegung einem Recycling zugeführt werden. Die Umweltrichtlinien des jeweiligen Landes müssen hierzu beachtet werden.

7 Zubehör Anschluss-Stecker

(nicht im Lieferumfang enthalten)

7.1 Gegenstecker M16 gerade

ACHTUNG

Empfehlung

- Litzenquerschnitt Leitungen ≤0.75 mm² (3 pol.) / Kabeldurchlass:
- Litzenquerschnitt Leitungen ≤0.75 mm² (7 pol.) / Kabeldurchlass: ø4 ... ø6 mm.
- Zubehör SIKO Art.Nr. "85057" (Buchse 3 pol. Betriebsspannung).
- Zubehör SIKO Art.Nr. "76141" (Buchse 7 pol. Eingänge).

Montage (Abb. 15)

- 1. (6) ... (10) über Kabelmantel schieben.
- 2. Kabel abisolieren.
- 3. Schirm (12) umlegen.
- 4. (5) auf Litzen schieben.
- 5. Litzen an (3) löten (entsprechend Anschlussplan).
- 6. Abstandhülse (4) aufweiten und über Litzen stülpen, zusammendrücken und auf (3) stecken. Schlitz (3) und Nut (4) müssen deckungsgleich sein.
- 7. (6) an (5) drücken, überstehenden Schirm abschneiden.
- 8. 2 und 7 aufschieben und mittels Montagewerkzeug (11) verschrau-
- 9. 8 in 9 stecken, beides in 7 schieben.
- 10. (10) mit (7) verschrauben.
- 11. (1) in (2) schieben.




Abb. 15: Gegenstecker M16 gerade

7.2 Gegenstecker M16 inkl. Kabel

Zubehör SIKO Art. Nr. "KVO3S1" (Buchse 3 pol. Betriebsspannung).

Deutsch

7.3 Gegenstecker M16 gewinkelt

ACHTUNG

Empfehlung

- Litzenquerschnitt Leitungen ≤0.75 mm² (3 pol.) / Kabeldurchlass: ø6 ... ø8 mm.
- Litzenquerschnitt Leitungen ≤0.75 mm² (7 pol.) / Kabeldurchlass: ø4 ... ø6 mm.
- Zubehör SIKO Art.Nr. "85058" (Buchse 3 pol. Betriebsspannung).
- Zubehör SIKO Art.Nr. "78088" (Buchse 7 pol. Eingänge).

Montage (Abb. 16)

- 1. Dichtungen (1) montieren (3x).
- Druckschraube ②, Klemmkorb ③, Dichtring ④, Schirmring ⑤ auf das Kabel auffädeln.
- 3. Kabel abmanteln, Schirm kürzen, Leiter abisolieren und verzinnen.
- 4. Litzen durch das Gehäuse (6) führen.
- 5. Schirmring (5) und Klemmkorb (3) montieren.
- 6. Druckschraube (2) leicht andrehen.
- 7. Litzen nach Anschlussplan an Kontakteinsatz (7) löten.
- 8. Positionshülse (8) in Winkelstellung montieren.
- 9. Kontakteinsatz (7) und Distanzhülse (9) einsetzen.
- 10. Deckel (10) einhaken.
- 11. Druckschraube (2) festziehen (ca. 10 ... 20 Ncm).




Abb. 16: Gegenstecker M16 gewinkelt

Ändern der Winkelstellung (Abb. 16 + Abb. 17)

ACHTUNG

Mehrfache Winkelverstellungen in eine Richtung, führen zu Leitungsverkürzung und Unterbrechung.

- 1. Druckschraube (2) aufdrehen.
- 2. Deckel (10) und Distanzhülse (9) entfernen.
- 3. Kontakteinsatz 7 und Positionshülse 8 leicht herausziehen und in gewünschte Winkelstellung (45° Schritte) verdrehen.
- 4. Deckel und Distanzhülse montieren, Druckschraube aufschrauben.




Abb. 17: Winkelstellungen

7.4 Gegenstecker M12 gewinkelt

ACHTUNG

Empfehlung

- Litzenquerschnitt Leitungen 0.14 ... 0.5 mm² / Kabeldurchlass: ø4 ... ø8 mm.
- Zubehör SIKO Art.Nr. "82804" (Buchse 5 pol. Profibus Ein).
- Zubehör SIKO Art.Nr. "82805" (Buchse 5 pol. Profibus Aus).

Montage (Abb. 18)

- 1. Druckmutter und Gehäuse auf das Kabel schieben.
- 2. Kabel abmanteln, Schirm kürzen.
- 3. Adern abisolieren und anschließen.
- 4. Gehäuse mit Einsatz verschrauben.
- 5. Druckmutter anziehen.






Abb. 18: Gegenstecker M12 gewinkelt

Ändern der Winkelstellung (Abb. 18)

ACHTUNG

Mehrfache Winkelverstellungen in eine Richtung, führen zu Leitungsverkürzung und Unterbrechung.

- 1. Buchseneinsatz aufdrehen, leicht herausziehen und in gewünschte Winkelstellung (45° Schritte) verdrehen.
- 2. Buchseneinsatz aufschrauben.

8 Technische Daten

| Mechanische Daten | | Ergänzung |
|-------------------------------|---|---|
| Welle | Edelstahl rostfrei | |
| Gehäuse | Aluminium | |
| Nenndrehmoment/-dreh- zahl | 6 Nm bei 150 min ⁻¹ (±10 %) | i = 30.6 (max. zul. Betriebs- punkt) |
| | 10 Nm bei 90 min ⁻¹ (±10 %) | i = 50 (max. zul. Betriebspunkt) |
| | 14 Nm bei 64 min ⁻¹ (±10 %) | i = 70.8 (max. zul. Betriebs- punkt) |
| Betriebsart | Aussetzbetrieb S3: 25 % ED, 10 min. | EN 60034-1 |
| Bremsmoment | Haltemoment durch Bremse entspricht min. dem Nenn- drehmoment der einzelnen Übersetzungen. | bei Umgebungstemperatur = 20 °C |
| Gewicht | ~3.2 kg | |

| Elektrische Daten | | Ergänzung |
|-------------------|---------------|--------------|
| Betriebsspannung | 24 V DC ±10 % | verpolsicher |
| Leistungsaufnahme | ~160 W | |

24 Technische Daten

| Elektrische Daten | | Ergänzung |
|-------------------|--------------|---------------------------------|
| Parameterspeicher | 10⁵ Zyklen | gilt auch für Kalibriervorgänge |
| Nennstrom | 6 A ±5 % | |
| Leerlaufstrom | 350 mA +20 % | (mit Getriehe) |

| Systemdaten | | Ergänzung |
|----------------|--------------------|-----------------------------|
| Auflösung | 1024 Inkremente | Single-Turn / 10 Bit |
| Verfahrbereich | 254 Umdrehung(en) | 8 Bit Multiturn (gerundet) |
| | 4094 Umdrehung(en) | 12 Bit Multiturn (gerundet) |

| Umgebungsbedingungen | | Ergänzung |
|---------------------------|-----------------------------|--|
| Umgebungstemperatur | 0 45 °C | |
| Lagertemperatur | -20 80 °C | |
| relative Luftfeuchtigkeit | | Betauung nicht zulässig |
| EMV | EN 61800-3, zweite Umgebung | Störfestigkeit / Immission |
| | EN 61800-3, C3 | Störaussendung / Emission |
| Schutzart | IP50 / IP54 / IP65 | EN 60529, bei montierten Gegensteckern |
| Schockfestigkeit | 500 m/s², 11 ms | EN 60068-2-27 |
| Vibrationsfestigkeit | ≤100 m/s², 50 Hz | EN 60068-2-6 |



9 Einbauerklärung

Originaleinbauerklärung für unvollständige Maschine

im Sinne der EG-Richtlinie 2006/42/EG über Maschinen (Anlage II B)

Hersteller/Bevollmächtigter der Dokumentation:

SIKO GmbH

Weihermattenweg 2 79256 Buchenbach Deutschland

Beschreibung und Identifizierung der unvollständigen Maschine:

Stellantrieb

Typ AG04B ab Gerätenummer 4000201 ab Monat/Jahr Juli/10

Folgende grundlegenden Sicherheits- und Gesundheitsschutzanforderungen nach Anhang I gemäß 2006/42/EG sind angewandt und eingehalten:

1.1.2; 1.1.3; 1.1.5; 1.5.1; 1.6.4; 1.7.1.1; 1.7.3

Die unvollständige Maschine entspricht weiterhin den Anforderungen folgender europäischer Richtlinien und den sie umsetzenden nationalen Rechtsvorschriften und den jeweilig nachfolgend genannten harmonisierten Normen:

• EMV-Richtlinie 2004/108/EG

Die speziellen technischen Unterlagen wurden gemäß Anhang VII Teil B der EG-Maschinenrichtlinie 2006/42/EG erstellt.

Wir verpflichten uns, diese den Marktüberwachungsbehörden auf begründetes Verlangen innerhalb einer angemessenen Zeit in elektronischer Form zu übermitteln.

Die Inbetriebnahme der unvollständigen Maschine wird so lange untersagt, bis die unvollständigen Maschine in eine Maschine oder Anlage eingebaut wurde, die den Bestimmungen der EG-Maschinenrichtlinie 2006/42/EG entspricht und für die eine EG-Konformitätserklärung gemäß Anhang II A vorliegt.

Buchenbach, den 11.05.2021

 $Han speter\, Thoma$

(Head of Design Department)

26

Table of contents

| 1 | Documentation 2 | 7 |
|----|--|---|
| 2 | Safety information | 7 |
| | 2.1 Intended use | 7 |
| | 2.2 Identification of dangers and notes | 7 |
| | 2.3 Target group | 8 |
| | 2.4 Basic safety information | |
| 3 | Identification | 9 |
| 4 | Installation | 0 |
| | 4.1 Mechanical mounting | 0 |
| | 4.2 Electrical Installation | 1 |
| | 4.3 Assignment of the DIP-switch | 3 |
| | 4.4 Pin assignment EX | |
| | 4.5 Pin assignment E1/PG (terminal box) | |
| 5 | Commissioning | 8 |
| 6 | Transport, Storage, Maintenance and Disposal 4 | 1 |
| 7 | Accessory connector 4 | 2 |
| | 7.1 Straight matting connector M16 | 2 |
| | 7.2 Mating connector M16 straight inclusive cable 4. | 3 |
| | 7.3 Right angle mating connector M16 | |
| | 7.4 Right angle mating connector M12 | |
| 8 | Technical data | 5 |
| 9 | Declaration of Incorporation 4 | 7 |
| 10 | Declaration of Conformity | 8 |



1 Documentation

The following documents describe this product:

- The data sheet describes the technical data, the dimensions, the pin assignments, the accessories and the order key.
- The mounting instructions describe the mechanical and electrical installation including all safety-relevant requirements and the associated technical specifications.
- The user manual and software description for commissioning and integrating the actuator into a fieldbus system.

These documents can also be downloaded at "http://www.siko-global. com/p/ag04b".

2 Safety information

2.1 Intended use

The AGO4B actuator serves for adjustment on plants and machines. The actuator is only intended for use in industrial applications that are not subject to special electrical or mechanical safety requirements.

- 1. Observe all safety instructions contained herein.
- 2. Arbitrary modifications and changes to this actuator are forbidden.
- 3. Observe the prescribed operating and installation conditions.
- 4. Operate the actuator exclusively within the technical data and the specified limits (see chapter 8).

2.2 Identification of dangers and notes

Safety notes consist of a signal sign and a signal word.

Danger classes



Immediate danger that may cause irreversible bodily harm resulting in death, property damage or unplanned device reactions if you disregard the instructions given.



Danger that may cause serious bodily harm, property damage or unplanned device reactions if you disregard the instructions given.



Danger that may cause minor injury, property damage or unplanned device reactions if you disregard the instructions given.

Safety information

NOTICE

Important operating information that may facilitate operation or cause unplanned device reactions if disregarded including possible property damage.



Signal signs

2.3 Target group

Installation instructions and User manual are intended for the configuration, commissioning and mounting personnel of plant or machine manufacturers who possess special expertise in drive technology. This group needs profound knowledge of an actuator's necessary connections and its integration into a complete machinery.

↑ WARNING

Insufficiently qualified personnel

Insufficiently qualified personnel cause personal injury, serious damage to machinery or actuator.

- Configuration, commissioning, mounting and maintenance by trained expert personnel only.
- This personnel must be able to recognize danger that might arise from mechanical, electrical or electronic equipment.

Qualified personnel are persons who

- are familiar with the safety guidelines of the electrical and automation technologies when performing configuration tasks;
- are authorized to commission, earth and label circuits and devices/ systems in accordance with the safety standards.

2.4 Basic safety information

DANGER

Danger of explosion

Do not use the actuator in explosive zones.



Unbraked actuator

Immediate loss of torque in case of voltage breakdown, interference and activation of the output stage/control unit supply. The actuator will not be braked.

Use external stopping devices (e. g. EMERGENCY-STOP holding brake).







Rotating parts

Bruising, rubbing, abrasing, seizing of extremities or clothes by touching during operation any rotating parts as for example clamping ring, torque support or hollow shaft.

Prevent people from access by installing protective facilities.

№ WARNING

Hot surfaces

Burns by temperatures >60 °C on the housing during operation.

- Prevent access to the housing.
- Protect temperature-sensitive parts of equipment using quards.

№ WARNING

Residential environment

High-frequency disturbances in residential environments.

This actuator is not suitable for use in a public low voltage system as those common in housing area.

CAUTION

High energetic recovery

In case of high moment of inertia in the customer plant and simultaneous braking, the actuator may switch over to generator operation; i. e., mechanical energy will be converted into electrical energy and fed back into the mains. The power supply unit must be able to absorb the developing energy to avoid destruction of other electric consumers.

- Use only power supply units with a high output capacitance (>10.000 μF) or power supply units capable of recovering energy.
- Use an appropriate brake resistor control if required.
- Check that all consumers are designed to absorb energetic recovery voltage.

CAUTION

External magnetic fields


Failures and data loss occur if strong magnetic fields influence the internal measuring system.

Protect the actuator from impact by external magnets.

3 Identification

Please check the particular type of unit and type number from the identification plate. Type number and the corresponding version are indicated in the delivery documentation.









4 Installation

4.1 Mechanical mounting

WARNING

Loss of type of protection

Loss of the type of protection caused by worn sealing rings in the ball bearing and radial shaft seals.

Operate the actuator within the admissible parameters (see chapter 8).

CAUTION

Destruction of main bearings

Improper installation (e. g. tension on the driving shaft) causes additional heat development and destruction of the actuator in the long term.

Ensure a low shaft and angle offset between shaft and accommodation bore by applying appropriate manufacturing methods (see Fig. 1 + Tab. 1).

CAUTION

Actuator failure

- When mounting pay attention to the IP type of protection (see chap-
- Owing to the type of protection screw all mating connectors (see chapter 7) to the actuator by applying ≥ 1 Nm.
- Do not open the actuator yourself (exception: see chapter 4.5 + 5).
- Avoid impact on the device.
- Do not modify the device in any way.

Preparing mounting (Fig. 1, Fig. 2, Fig. 3):

- 1. Make bore (øD) with distance (L1) to the driving shaft (2).
- 2. Observe length (L2) and diameter (ød) of shaft (2).
- 3. Untighten the M5 screw in the torque support (1) and M4 screw in the clamping ring (3).

Mounting (Fig. 1, Fig. 2, Fig. 3):

- 1. Slide the actuator on the shaft (2) until the torque support has reached the stopper (1). You may slightly adjust the torque support to the installation conditions via a long hole.
- 2. Tighten the clamp ring screw (3) by applying 10 Nm, or headless pin
- 3. Tighten the screw for the torque support (1) by applying ≤2 Nm.





Fig. 1: Mounting dimensions

| dim.øD | ø13 ø14 |
|---------|--------------|
| dim. L1 | 106.7 |
| dim. L2 | 40 45 |
| dim.ød | Ø20f8; Ø14f8 |

Tab. 1: Mounting dimensions








Fig. 3: Fastening torque for screws

- 1 Torque support
- 2 Shaft
- 3 Champ ring screw

4.2 Electrical Installation



Destruction of parts of equipment and loss of regulation control

- Do not disconnect or close live connections.
- Perform wiring work in the de-energized state only.
- Use strands with suitable ferrules.
- Prior to switching on check all mains and plug connections.
- Switch on operating voltage together with downstream electronics (e. g., control unit).

AGO4B Installation

WARNING

Unforeseen actions of the actuator or other devices

The actuator is protected against EMC irradiation and emission (electromagnetic compatibility). Excessive external EMC radiation may trigger unforeseen actuator actions (including destruction of the actuator; the actuator being set in motion; loss of position value) Devices that are not EMC protected and those operated in direct vicinity to the actuator may be disturbed.

- Perform wiring work in accordance with the EMC measures IEC 61800-3 and chapter 4.2.
- Check the correct execution of the EMC measures.

WARNING

Danger of fire

Fuse protection is required as a protection against damage caused by defective devices.

- Electronic automatic fuses of the E-T-A company or load circle monitoring devices of the Murr Elektronik company are suitable solutions for this purpose.
- For the nominal currents refer to the technical data in chapter 8.

! CAUTION

Electromagnetic compatibility (EMC)

The following measures are required in order to ensure the actuator's electromagnetic compatibility:

- Provide a separate power adapter for the supply of one or multiple SIKO actuators.
- ▶ All lines for connecting the actuator must be shielded.
- The cable shield must be applied to both sides.
- ▶ The retractable ferrite (supplied with the AG04B) is to be attached to the supply line near the 3-pole connector.
- The drive is to earthed via the flat connection with a strand section of ≥4 mm².

NOTICE

Basically, all connections are protected against external interference. Choose a place of operation that excludes inductive or capacitive interference influences on the actuator. When mounting the system keep a maximum possible distance from lines loaded with interference. If necessary, provide additional installations including screening shields or metallized housings.

Admissible power input

NOTICE

Supply for the actuator shall be sized sufficiently. When accelerating, power input may be higher than nominal current for a short period. The voltage values are a function of the device design and can be referred to in the technical data in chapter 8.





Motor control + output stage

- Wire cross section ≥0.5 mm²
- Motor control and output stage are both supplied via the operating voltage connection.

Digital inputs

15 ... 30 V DC; typ. 10 mA

4.3 Assignment of the DIP-switch

| Switch | Assignment |
|-----------|--|
| SW1-SW7 | Bus address: see chapter Profibus - address setting |
| SW8 | No function: position always to OFF |
| SW9 | Terminal connection method EX: position always to ON Terminal connection method E1/PG: see chapter Pin assignment E1/PG, Terminal block X3 |
| SW10 | Limit switch inputs disable: see chapter limit switch inputs 1+2 |
| SW11+SW12 | Bus termination: see chapter Profibus - bus termination |

4.4 Pin assignment EX




Fig. 4: Connection EX

- 1 Earthing (3x 6.3)
- 2 Operating voltage
- (3) Inputs
- 4 Bus-In
- (5) Bus-Out

Operating voltage

Plug pin 3 pin.

For mating connector and cable extension accessories see chapter 7.

| PIN | Designation |
|-----|-------------|
| 1 | +24 V |
| 2 | Enable |
| 3 | GND |



viewing side = plug-in side




Profibus-DP

- Bus-In: pluq pin 5 pin.
- Bus-Out: socket contact 5 pin.

For mating connector and cable extension accessories see chapter 7.

| PIN | Designation | | |
|-----|-------------|--|--|
| 1 | nc | | |
| 2 | BUS A | | |
| 3 | nc | | |
| 4 | BUS B | | |
| 5 | nc | | |



Inputs

NOTICE

There is no galvanic isolation of the digital inputs with the EX type of connection!

Plug pin 8 pin.

For mating connector and cable extension accessories see chapter 7.

| PIN | Designation |
|-------|----------------|
| 1 | Limit switch 1 |
| 2 | Limit switch 2 |
| 3 | Input 1 |
| 4 | Input 2 |
| 5 - 7 | nc |



viewing side = plug-in side




Fig. 5: Input circuit/digital inputs at connection type EX

4.5 Pin assignment E1/PG (terminal box)

A DANGER

Overload

Overload of the conductors with looping through the +24 V/GND/shield connections.

Do not exceed the total current of 20 A!





Destruction of the actuator

Nonobservance results in the loss of inverse-polarity protection and, therefore, in the destruction of the actuator.

 Use the terminal strip X3.7 (GND) connection only to generate a bridge to the terminal strip X3.6 (EXT_GND) connection.



Actuator failure

The type of protection will be lost if the "Operating voltage Out", "Bus-Out" or "Input"connections are not used.

- Use the supplied caps in the terminal box.
- ▶ When mounting the cover take care that the gasket is seated correctly.




Fig. 6: Connection E1/PG (5x PG9)

- 1 Earthing (3x 6.3)
- (2) Operating voltage In
- (3) Operating voltage Out
- (4) Inputs
- 5 Bus-In
- 6 Bus-Out

Terminal box assembly/disassembly

The terminal block can be accessed after unscrewing the 6 screws and removing the cover.




Fig. 7: Mounting example (cable not provided!)

- 1 Terminal block X1
- 2 Terminal block X2
- 3 Terminal block X3
- 4 PCB no.



Terminal block X1 (Operating voltage)

Clamping range without ferrule: 0.13 ... 2.5 mm².

Clamping range with ferrule (6 mm): 0.25 ... 1.5 mm².

When selecting the core cross section consider the cable length accordingly (power loss).

| Terminal X1 | Designation |
|-------------|--------------------------------|
| 1 | +24 V (Operating voltage Out) |
| 2 | +24 V (Operating voltage In) |
| 3 | GND (Operating voltage Out) |
| 4 | GND (Operating voltage In) |
| 5 | Screen (Operating voltage Out) |
| 6 | Screen (Operating voltage In) |

Terminal block X2 (Profibus-DP)

Profibuscable according to the EN 50170 standard.

| Terminal X2 | Designation |
|-------------|-------------|
| 1 | BUS B |
| 2 | BUS A |
| 3 - 8 | nc |
| 9 | BUS A |
| 10 | BUS B |

Terminal block X3 (inputs)

NOTICE

At the connection type E1/PG, the inputs are always galvanically isolated from GND. In order to undo galvanic isolation, connect the signals terminal strip X3.6 (EXT_GND) and terminal strip X3.7 (GND). If the PCB no. 84403.2 applies: The DIP switch no. 9 must be actuated (on) to lift the galvanic isolation. The PCB no. between X1 and X2 can be seen on the PCB surface (Fig. 7).

Clamping range without ferrule: 0.2 ... 1.5 mm².

Clamping range with ferrule (8 mm): 0.25 ... 1.5 mm².





Fig. 8: Input circuit/digital inputs at connection type E1/PG



| Terminal X3 | Designation |
|-------------|----------------|
| 1 | Limit switch 1 |
| 2 | Limit switch 2 |
| 3 | Input 1 |
| 4 | Input 2 |
| 5 | Enable |
| 6 | EXT_GND |
| 7 | GND |

Connection cable E1/PG

- Prepare wire according to Fig. 9. Ferrules must have gas-tight square crimping.
- 2. Open the device (see chapter 4.5) and unscrew the PG-screws.



| | A | В | C |
|-------------------|----|---|----|
| Operating voltage | 70 | 6 | 12 |
| Profibus-DP | 70 | 8 | 12 |
| Inputs | 70 | 8 | 12 |
| | | | |

Fig. 9: Cable

Tab. 2: Cable dimension

1) Strands stripped and untinned

Connection cable screwing

- 1. Push nut+gasket ①, washer ② (inner-ø > inner-ø washer ④) and washer ④ onto the cable.
- 2. Put the wire screening ③ over the washer's ② outer surface.
- 3. Push strands through the screw hole (5). Insert parts (4), (3), and (2) into the screw hole (5).
- 4. Screw on the nut 1 and attach the complete bolting to the hood.
- 5. Connect strands to the terminal of the device (see chapter 4.5).




Fig. 10: Cable screwing PG9

AG04B



Earthing connection (PE)

For protection against interference, the screens of the signal lines and the power line must be connected on both sides. Potential differences cause inadmissible currents on the screen. Apply the PE connection ① to the protective conductor potential below the connecting plugs (see Fig. 4 or Fig. 6). Use 6.3 mm flat connectors with short strands 2.5 ... 4 mm² (not in the scope of delivery). For multiple actuators we recommend connecting the earthing to a ground bar ① (see Fig. 11).




Fig. 11: Ground bar

5 Commissioning



Latch-up effects

The driver's output stage is damaged.

▶ The device's operating voltage must be switched on together with the downstream electronics unit (e. q. control).

Please carefully read the information on the actuator's mechanical and electrical connection. This will ensure a trouble free commissioning and operation.

Before operation, please check again:

- that the supply voltage's polarity is correct.
- correct connection of cable and signal lines.
- secure actuator fixation on the hollow shaft.
- correct mounting and functioning of the limit switches.








Fig. 12: DIP switch

- 1 DIP switch
- (2) Profibus-LED (orange)
- (3) Status-LED (red/green)
- (4) Key for inching mode ccw motion (view on clamp ring)
- (5) Key for inching mode cw motion (view on clamp ring)

Profibus-DP

NOTICE

- The sense of rotation in inching operation is independent from the "Sense of rotation" parameter.
- Inching operation is only enabled if the Profibus State machine of the actuator is not in the Data Exchange state.

After correct mounting and wiring, the actuator can be activated by turning on the 24 V power supply.

Enable input

A high level must be applied to the enable input in order to enable drive activation. Therefore, wiring of this input is mandatory. The status LED will be lit red if no high level is applied to the enable input. Green lighting of the status LED signals activation of the enable input and readiness for operation of the drive.

Limit switch inputs 1+2

The two low-active limit switch inputs can be inactivated via the SW10 DIP switch (see Fig. 12).

| SW10 | Limit switch | Remark |
|------|--------------|--|
| OFF | active | Wiring of the limit switches is mandatory. |
| ON | deactivated | No wiring of the limit switches required. |

The arrangement of the limit switches is independent of the parameterized sense of rotation:

Commissioning




Fig. 13: Limit switch

- (1) Limit switch 1
- Limit switch 2

The lit switch inputs are dedicated to the mechanical sense of rotation (see Fig. 13). With limit switch 1 in the active state, motor adjustment in the "limit switch 1" direction is no longer possible. The same applies to limit switch 2 accordingly.

Inputs 1+2

The two additional inputs are low – active.

Profibus - address setting



Actuator failure

- Owing to the type of protection, unscrew the Allen head screws (1) only (see Fig. 14).
- With the screws 1 of the cover 2 loosened, the drive's type of protection is no longer ensured.
- Set parameter on the DIP switch (3).
- When remounting the screws (1) take care that the seals (4) are seated correctly!

NOTICE

The DIP switch settings are read in only during switching on voltage supply. Changing the slave address during operation has no effect.

After unscrewing the 4 screws (1) and removing the cover (2), the DIP switch (3) can be accessed for address setting.




Fig. 14: Address setting

- 1) Screws
- 2 Cover
- DIP switch
- (4) Seal



The slave address is entered via switches 1 - 7 in binary format. The setting of address 127 is internally set into address 126.

This is illustrated in the following table:

| SW1 [2º] | SW2 [2 ¹] | SW3 [2 ²] | SW4 [2³] | SW5 [2 ⁴] | SW6 [2 ⁵] | SW7 [2 ⁶] | set slave address |
|-------------|--------------------------|--------------------------|-------------|--------------------------|--------------------------|--------------------------|----------------------|
| OFF | OFF | OFF | OFF | OFF | OFF | OFF | 0 |
| ON | OFF | OFF | OFF | OFF | OFF | OFF | 1 |
| OFF | ON | OFF | OFF | OFF | OFF | OFF | 2 |
| ON | ON | OFF | OFF | OFF | OFF | OFF | 3 |
| : | : | : | : | : | : | : | : |
| OFF | OFF | ON | ON | ON | ON | ON | 124 |
| ON | OFF | ON | ON | ON | ON | ON | 125 |
| OFF | ON | ON | ON | ON | ON | ON | 126 |
| ON | ON | ON | ON | ON | ON | ON | 126! |

Profibus bus terminator

The internal bus terminator can be activated via DIP switches 11 + 12:

| SW11 | SW12 | Bus terminator |
|------|------|----------------|
| OFF | OFF | deactivated |
| ON | ON | active |

6 Transport, Storage, Maintenance and Disposal

Transport and storage

Handle, transport and store actuators with care. Pay attention to the following points:

- Transport and / or store actuators in the unopened original packaging.
- Protect actuators from harmful physical influences including dust, heat and humidity.
- Do not damage connections through mechanical or thermal impact.
- Prior to installation inspect the actuator for transport damages. Do not install damaged actuators.

Maintenance

With correct installation according to chapter 4 the actuator requires no maintenance. The actuator has received lifetime lubrication and need not be lubricated under normal operating conditions.



Disposal

The actuator's electronic components contain materials that are harmful for the environment and are carriers of recyclable materials at the same time. Therefore, the actuator must be recycled after it has been taken out of operation ultimately. Observe the environment protection guidelines of your country.

Accessory connector

(not included in the scope of delivery)

7.1 Straight matting connector M16

NOTICE

Advice

- Strand cross sections of lines ≤0.75 mm² (3 pin) / cable feed-through: ø6 ... ø8 mm.
- Strand cross sections of lines ≤0.75 mm² (7 pin) / cable feed-through: ø4 ... ø6 mm.
- Accessory SIKO art. no. "85057" (socket contact 3 pin operating voltage).
- Accessory SIKO art. no. "76141" (socket contact 7 pin inputs).

Mounting (Fig. 15)

- 1. Slip 6 ... 10 over outer cable.
- 2. Strip cable.
- 3. Turn down screening (12).
- 4. Push (5) onto ferrules.
- 5. Solder cable to (3) (according connection diagram).
- 6. Open spacer (4) and put it over ferrules, squeeze and push it onto (3). Slot and keyway of (3) and (4) must align.
- 7. Press 6 and 5 together; cut prodruding screening.
- 8. Push (2) and (7) together and screw (11) using appropriate tool.
- 9. Push (8) into (9) and slide both parts into (7).
- 10. Screw (10) and (7) together.
- 11. Push (1) into (2).






Fig. 15: Straight matting connector M16

7.2 Mating connector M16 straight inclusive cable

Accessory SIKO art. no. "KVO3S1" (socket contact 3 pin operating voltage).

7.3 Right angle mating connector M16

NOTICE

Advice

- Strand cross-section of lines ≤0.75 mm² (3 pin) / cable feed-through: ø6 ... ø8 mm.
- Strand cross-section of lines ≤0.75 mm² (7 pin) / cable feed-through: ø4 ... ø6 mm.
- Accessory SIKO art. no. "85058" (socket contact 3 pin operating voltage).
- Accessory SIKO art. no. "78088" (socket contact 7 pin inputs).

Mounting (Fig. 16)

- 1. Mount seals (1) (3x).
- 2. Stringing pressing screw (2), pinch ring (3), seal (4), shielding ring (5).
- 3. Dismantle cable, shorten screening, strip and tin conductor.
- 4. Thread-up wires through the housing (6).
- 5. Mount shielding ring (5) and pinch ring (3).
- 6. Turn on the pressing screw (2) very slightly.
- 7. Solder wires on insert (7).



Accessory connector

- 8. Mount positioning sleeve (8) in angled position.
- 9. Set in insert (7) and distance sleeve (9).
- 10. Mount cover (10).
- 11. Fix pressing screw (2) (approx. 10 ... 20 Ncm).




Fig. 16: Right angle mating connector M16

Changing the angle position (Fig. 16 + Fig. 17)

NOTICE

Multiple angle adjustments to a single direction cause shortening of the line and break.

- 1. Slight unscrew pressing screw (2).
- 2. Remove cover (10) and distance sleeve (9).
- 3. Slightly pull out female contact 7 and positioning sleeve 8 and rotate to desired angular position (in steps of 45°).
- 4. Mount cover and distance sleeve; tighten pressure screw.




Fig. 17: Angle positions



7.4 Right angle mating connector M12

NOTICE

Advice

- Strand cross-section of lines 0.14 ... 0.5 mm² / cable feed-through: ø4 ... ø8 mm.
- Accessory SIKO art. no. "82804" (socket contact 5 pin Profibus-In).
- Accessory SIKO art. no. "82805" (socket contact 5 pin Profibus Out).

Mounting (Fig. 18)

- 1. Slide the pressure nut and housing along the cable.
- 2. Strip the cable, shorten the screen.
- 3. Strip wires and connect.
- 4. Screw housing with insert.
- 5. Tighten pressure nut.




Fig. 18: Right angle mating connector M12

Changing the angle position (Fig. 18)

NOTICE

Multiple angle adjustments to a single direction cause shortening of the line and break.

- 1. Turn on female contact, slightly pull out and rotate to desired angular position (in steps of 45°).
- 2. Screw on female contact.

8 Technical data

| Mechanical data | | Additional information |
|-----------------|-----------------|-------------------------------|
| Shaft | stainless steel | |
| Housing | aluminum | |

| Mechanical data | | Additional information |
|----------------------------|--|--------------------------------------|
| Nominal torque/rated speed | 6 Nm at 150 min ⁻¹ (±10 %) | i = 30.6 (max. adm. operating point) |
| | 10 Nm at 90 min ⁻¹ (±10 %) | i = 50 (max. adm. operating point) |
| | 14 Nm at 64 min ⁻¹ (±10 %) | i = 70.8 (max. adm. operating point) |
| Operating mode | S3 intermittent duty: 25 % DC, 10 min. | EN 60034-1 |
| Brake momentum | Brake-induced stop momentum corresponds at least to the nominal torques of the individual transmissions. | at ambient temperature = 20 °C |
| Weight | ~3.2 kg | |

| Electrical data | | Additional information |
|-------------------|---------------|---|
| Operating voltage | 24 V DC ±10 % | reverse polarity protected |
| Power input | ~160 W | |
| Parameter memory | 10⁵ cycles | also applies to calibration pro- cedures |
| Rated current | 6 A ±5 % | |
| No-load current | 350 mA ±20 % | (with transmission) |

| System data | | Additional information |
|--------------|--------------------|-----------------------------|
| Resolution | 1024 increment(s) | single turn / 10 bit |
| Travel range | 254 revolution(s) | 8 bit multi turn (rounded) |
| | 4094 revolution(s) | 12 bit multi turn (rounded) |

| Ambient conditions | | Additional information |
|----------------------|--------------------------------|-------------------------------------|
| Ambient temperature | 0 45 °C | |
| Storage temperature | -20 80 °C | |
| Relative humidity | | condensation inadmissible |
| EMC | EN 61800-3, second environment | interference resistance / immission |
| | EN 61800-3, C3 | emitted interference / emission |
| Protection category | IP50 / IP54 / IP65 | EN 60529, mating connectors mounted |
| Shock resistance | 500 m/s ² , 11 ms | EN 60068-2-27 |
| Vibration resistance | ≤100 m/s², 50 Hz | EN 60068-2-6 |

9 Declaration of Incorporation

Original Declaration of Incorporation of an Incomplete Machine according to the Machinery Directive 2006/42/EC (Appendix II B)

Manufacturer/commissioner of the documentation:

SIKO GmbH

Weihermattenweg 2 79256 Buchenbach Germany

Description and identification of the incomplete machine:

Actuator

Type AG04B
Starting with device no. 4000201
Starting with month/year Juli/10

The following basic safety and health protection requirements according to Appendix I of Directive 2006/42/EC are applied and adhered to:

1.1.2; 1.1.3; 1.1.5; 1.5.1; 1.6.4; 1.7.1.1; 1.7.3

Furthermore, the incomplete machine complies with the requirements of the following European Directives and the implementing national legal provisions and the respective harmonized standards as indicated below:

EMC Directive 2004/108/EG

The special technical documents have been prepared according to Appendix VII Part B of the Machinery Directive 2006/42/EC.

We obligate ourselves to transmit said documents in electronic form to the market supervisory authorities upon reasonable request within a reasonable timing.

Commissioning of the incomplete machine is prohibited until the incomplete machine has been installed into machinery that complies with the provisions of the EC Machinery Directive 2006/42/EC and if the EC Declaration of Conformity pursuant to Appendix II A is available for the machinery.

Buchenbach, 11/05/2021

Hanspeter Thoma

(Head of Design Department)

10 Declaration of Conformity

In accordance with UK Government Guidance.

1. Product Model / Type:



| Model | Batch / Serial |
|-------|----------------|
| AG04B | 50010890 |

2. Manufacturer:

Name: SIKO GmbH

Address: Weihermattenweg 2, 79256 Buchenbach, Germany

- 3. This declaration is issued under the sole responsibility of the product manufacturer.
- 4. The object of the declaration described above is in conformity with the relevant UK Statutory Instruments and their amendments:

| 2016 No 1091 | The Electromagnetic Compatibility Regulations 2016. |
|--------------|---|
| 2012 No 3032 | The Restriction of the Use of Hazardous Substances in Electrical and Electronic Equipment Regulations 2012. |
| 2008 No 1597 | The supply of Machinery (Safety) Regulations 2008. |

5. We hereby declare that the product described above, to which this declaration of conformity refers to, is in conformity with the essential requirements of the following standards:

| Reference & Date | Title |
|---------------------|---|
| DIN EN 61800-3:2005 | Adjustable speed electrical power drive systems - Part 3: EMC |
| | requirements and specific test methods. |

6. Additional Information:

The technical documentation for the machinery / product is available from:

Supplier: Gapp Automation Ltd
Name: Michael Bannister
Address: Unit 6 Kempston Court

Kempston Hardwick, Bedford, MK43 9PQ, United Kingdom

Signed for & on behalf of: SIKO GmbH

Place of issue: 79256 Buchenbach, Germany


Date of Issue: 3 February 2022 Name: Hanspeter Thoma


Function: Head of Product Development


Signature:

i. V. H. floura











SIKO GmbH

Weihermattenweg 2 79256 Buchenbach

Telefon/Phone +49 7661 394-0 Telefax/Fax

+49 7661 394-388

E-Mail

info@siko-global.com
Internet

www.siko-global.com

Service

support@siko-global.com